



Underwriters Laboratories Inc.®

MSPS

**IMO INDUSTRIES INC
BARKSDALE CONTROLS DIV
MR D MCAFEE
3211 FRUITLAND AVE
PO BOX 58843
LOS ANGELES CA 90058**

Your most recent listing is shown below. Please review this information and report any inaccuracies to the UL Engineering staff member who handled your Assignment.

**MFHX2 February 9, 1994
Component - Switches**

**IMO INDUSTRIES INC BARKSDALE CONTROLS DIV MH8147 (S)
3211 FRUITLAND AVE PO BOX 58843 , LOS
ANGELES CA 90058**

Pressure-operated switch, Model E1S-H16-Q20.
Pressure-operated switch, Models SPS, MSPS and CMSPS, followed by DD, EE, FF, JJ, KK, LL, MM, NN or XX, followed by 05, 15 or 100, may be followed by SS, may be followed by V or E, may be followed by F1 thru F10, may be followed by Q1 thru Q99.
Pressure-operated switch, Models SPS-KK05, -15; may have additional suffixes, may have prefix "M".
Marking: Company name and model designation.

See General Information Preceding These Recognitions.

For use only in equipment where the acceptability of the combination is determined by Underwriters Laboratories Inc.

Reports: July 29, 1977; November 24, 1986; June 23, 1987.

Replaces MH8147 dated January 18, 1990.
339536001 Underwriters Laboratories Inc.® D110019736
21

For information on placing an order for UL Listing Cards in a 3 x 5 inch card format, please refer to the enclosed ordering information.

UNDERWRITERS LABORATORIES INC.

RECEIVED IN

FEB 22 1994

An independent, not-for-profit organization testing for public safety

ENGINEERING

333 Pfingsten Road
Northbrook, Illinois 60062-2096, USA
708/272-8800
Telex: 6502543343
FAX No. (708) 272-8129

1285 Walt Whitman Road
Melville, L.I., New York 11747-3021, USA
516/271-6200
Telex: 6852015
FAX No. (516) 271-8259

1655 Scott Blvd.
Santa Clara, California 95050-4166, USA
408/985-2400
Telex: 184219
FAX No. (408) 296-3256

12 Laboratory Drive
P.O. Box 13895
Research Triangle Park,
North Carolina 27709-3895, USA
919/549-1400
Telex: 4937928
FAX No. (919) 549-1842